MINUTES RESTORATION ADVISORY BOARD NAVY AREA-WIDE

A Restoration Advisory Board meeting for the Navy Area-Wide Installation Restoration sites was held on Wednesday, October 6, 1999 at the Hyatt Regency's Ballroom C at 7:00 p.m. Enclosure (1) is a list of attendees. A copy of the minutes from the July 14, 1999 RAB meeting was provided.

Lieutenant Prather did the opening remarks. He introduced the key personnel. Speakers for this meeting were: Ms. Darlene Ige, Head of the Installation Restoration (IR) Branch, Ms. Helen Lam, Remedial Project Manager and Mr. Cowan Azuma, Remedial Project Manager. In addition, Mr. Mike Gawel, Co-Chairperson, mentioned the speakers would be presenting certain topics concerning the environmental cleanup updates at various IR sites.

- 1. Ms. Darlene Ige presented an overview update on the progress of environmental cleanup for the Installation Restoration (IR) sites. Handouts (enclosure (2)) were available for the public.
- 2. Mr. Cowan Azuma presented the following:
- a. An update on the cleanup at the South Finegayan Construction Battalion Landfill, U.S. Navy Public Works Center (enclosure (3)) was presented. He provided the results of the dye trace study, results of gas monitoring, and results of the first quarter groundwater monitoring updates. The following questions and answers were addressed:
 - Q1: After the cap was installed, the dye was not detected at any of the monitoring wells, where would you guess the dye would have gone? Would it have gone lower than your sampling points?
 - A: The sampling points in these wells are down to groundwater which is approximately 300 plus feet below the ground surface. That is where we were taking our samples. My guess is that the dye went above the groundwater.
 - Q2: What was the purpose of the dye trace study and what did you learn from it?
 - A: The purpose of the dye trace study was to determine sampling locations for the long-term groundwater monitoring program. What we learned from it was that there are preferred channels in this karst environment on Guam which we expected. We just didn't know exactly where the sampling locations would be.
 - Q3: How much dye was poured into it?
 - A: We poured in two gallons of water soluble dye.

Q4: Was there any precipitation?

A: No, there was not. We were pouring water into the sinkhole. After we introduce the dye, we followed with 2,000 gallons of water. Also, the seven monitoring wells have pumps in them that would pump water at a rate of three to five gallons per minute. All of this water discharge was reintroduced into the sink hole, flushing it out. It amounted to over 10,000 plus gallons a day and it was done during the two weeks of the dye trace study.

Q5: What was the time length from the time you injected the dye to the time the dye was detected?

A: We detected dye at the springs the very next day from the first sampling effort. In the sampling effort, activated charcoal (which absorbs the dye) was placed at the springs prior to introducing the dye. The dye was then introduced and during the first sampling effort, the charcoal was recovered and submitted to the Lab. These samples had indication of dye from both springs.

Q6: During the previous dye trace, one of the wells showed detection of dye. Was that an injection point, do you recall?

A: In the first dye trace study, dye was introduced into one of the monitoring wells (DW-3), which was a deep well leading down to the groundwater which was within the landfill limits.

Q7: The two coastal springs that detected dye, were they seepage cells where water moves on the beach sand or actual point sources?

A: The water is coming out of a fracture. There are photos available showing that during different tides sand covers the spring; but when the sand retrieves, its coming out from the fracture.

Q8: Is the purpose of the monitoring to basically see if the cleanup is working, the capping of the landfill?

A: That's correct.

Q9: How much base data before any of the capping operations do we have? How much sampling have we done?

A: We have information in the Remedial Investigation report and the baseline sampling data which was obtained back in May of this year.

Q10: Are the baseline data from the same monitoring wells that are not showing any dye?

A: Correct, but we also took baseline data at the springs where we did find dye.

- Ms. Helen Lam presented an update of the status on the seawall construction at the Orote Landfill (enclosure (4)). 70 percent of the construction activity at the site has been completed. The following questions and answers are provided:
 - Do you think the seawall will be stronger than the adjacent seawall next door?
 - The seawall was designed based on the 100 year storm event. A:
 - Q2: If an earthquake occurred and breaks the seawall, will it be rebuilt? Who will be held responsible?
 - The Navy will be held liable for repairing the seawall. According to A: Comprehensive Environmental Response, Compensation and Liability Act, it is indefinite. If there's a failure in design, the Navy will be liable. Because there are still contamination on site that the Navy is responsible for, they will continue to be responsible.
 - Q3: The Deputy of Guam Environmental Protection Agency inquired who had visited the site?
 - Majority of the public attendees had visited the site. Per Lieutenant A: Prather, if anyone is interested in visiting the site, call his office and he will make site visit arrangements.
- Lieutenant Prather concluded the meeting by thanking everyone for being there. The meeting adjourned at 8:00 p.m. The next RAB meeting will be held on February 9, 2000.

Approved by:

Community Co-Chairperson

AIG S. PRATHER, LT, CEC, USN, P.E.

Navy Co-Chairperson

LIST OF ATTENDEES NAVY AREA-WIDE RESTORATION ADVISORY BOARD MEETING, Oct 6, 1999

NAME	AGENCY/ADDRESS	CONTACT NO.	EMAIL
Oliver Bordallo	CB & B		
Jesse T. Cruz	Guam EPA	475-1664	Jtcruz@ns.gu
Clinton William Huntington, II	Leo Palace Resort		
Walter S. Leon Guerrero	Guam EPA	475-1645	Walterlg@ns.gu
Scott Denzer	Guam EPA	475-1650	Sdenzer@ns.gu
David W. Longa	Guam EPA	475-1658/59	
Patrick Ono	IT	(808) 682-1616 ext. 504	Pono@theitgroup.c om
Tsutsui, Roy	COMNAVMARIANAS	339-5094 339-4363	N451@guam.navy. mil
Nestor Acedera	IT	(808) 474-3065	Nacedera@theitgro up.com
Hiphil S. Clemente	PWC Guam	339-4610/339-2035	Clementh@pwcgua m.navy.mil
Lawrence Lansdale	Ogden		
Danko Taborosi	WERI-UOG		Dankot@campus.u nivguam.edu.gu
Anthony Hoover	COMNAVMARIANAS	339-8181/ 339-4363	N453@guam.navy. mil
Joseph Gallo	COMNAVMARIANAS	339-7055	N4531@guam.nav y.mil
Mike Breitenstein	Moffatt & Nichol Engineers		
Eric Wetzstein	Ogden		
ENS C.A. Gonzales, NSCC	USNSCC .	339-8676 (Work)	Cgonzal@odedode a.edu
Chris Lund	Dames & Moore		
Mike Gawel	Guam EPA	475-1662/477-9402	Mgawel@ns.gu
Jordan Kaye	Guam EPA		Jkaye@ns.gu
Victor Wuerch	Guam EPA	475-1630	Vwuerch@ns.gu

LIST OF ATTENDEES NAVY AREA-WIDE RESTORATION ADVISORY BOARD MEETING, Oct 6, 1999

NAME	AGENCY/ADDRESS	CONTACT NO.	EMAIL
Richard Gray	IT	546-3722/3724	Rgray@theitgroup.
Darlene Ige	PACDIV	(808) 474-4520	lgedy@efdpac.navf ac.navy.mil
Helen Lam	PACDIV	(808) 474-8911	Lamhs@efdpac.na vfac.navy.mil
Cowan Azuma	PACDIV	(808) 474-5389	Azumach@efdpac. navfac.navy.mil
Vance S. Eflin	Guam EPA	475-1652/477-9402	Veflin@ns.gov.gu
LT Craig Prather	COMNAVMARIANAS (N45) RAB Navy Co- Chair	339-4365/7051	N45@guam.navy. mil
Robyn Matsumoto	IT	546-3715/564-3724	Rmatsumoto@theit group.com
Mark Kawakami	IT	546-3721/564-3724	Mkawakami@theitg roup.com
Mike Kahl	IT	564-3717	Mkahl@theitgroup.
Tony Roberson	PWC Guam	339-3711/333-2035	900@pwcguam.na vy.mil
Eleanor D. Mantanona	PWC Guam	339-4522	Mantanoe@pwcgu am.navy.mil
Erlinda Barlan	PWC Guam	339-7348/333-2035	Barlane@pwcguam .navy.mil
Joe V. Cruz	Guam EPA	475-1605	



SEAWALL CONSTRUCTION and LANDFILL COVER DESIGN Orote Landfill Site COMNAVMARIANAS, Guam

Fact Sheet No. 6

October 1999

This Fact Sheet describes the ongoing cleanup of contamination at U.S. Naval Forces Marianas (COMNAVMARIANAS) Guam under the Installation Restoration (IR) Program. This is one in a series of informational flyers that will be issued periodically throughout the cleanup process.

INTRODUCTION

This fact sheet provides updated information regarding the construction activities at the Orote Landfill Site, COMNAVMARIANAS Guam. Construction of the seawall began in March 1999 and will continue until December 1999. The draft design for the landfill cover has been completed. The previous fact sheet dated July 1999 discussed the seawall construction and a pilot test to investigate the effectiveness of the proposed revegetation plan.




Figure 1. Location Map

BACKGROUND

The Orote Landfill Site occupies approximately 9.4 acres of land within COMNAVMARIANAS on the southern portion of the Orote Peninsula (Figures 1 and 2). The Orote Landfill was used for disposal of residential, industrial, and construction wastes from approximately 1944 to 1969. The face of the cliff that surrounds the landfill was reportedly the most active disposal area. Flammable material was burned, and the ashes were buried on the cliff above the nearby cove. Nonflammable material were either buried behind the cliff or bulldozed over the cliff onto the beach. The beach contained a large amount of rusted metal and other debris. Erosion of the landfill cliff had been observed as a source of the debris on the beach.

SEAWALL AND LANDFILL COVER

The unprotected cliff at the Orote Landfill site was observed to be retreating due to erosion by the sea. It was recognized that as the cliff has eroded, landfill material that is exposed may be transported to the Philippine Sea. Additionally, the cliff must be stabilized before a landfill cap can be applied over the site. A seawall was therefore included in the Orote Landfill project to stabilize the existing cliff.

The purpose of the seawall is to protect the site from further erosion, enable a landfill cap to be placed on the landfill, and to

cap the landfill material currently exposed on the cliff. Further erosion will be prevented since waves will impact the seawall rather than the cliff. A liner is included as part of the design to prevent the waves from coming into contact with the landfill materials. The landfill cover will have a liner that overlaps the liner beneath the seawall forming a continous low permeability cap over the exposed landfill materials.




Figure 2. Map of site showing the approximate boundary of the landfill and location of seawall that is under construction

CONSTRUCTION ACTIVITIES

Construction activities on the seawall began in March 1999. Currently the seawall is approximately 70% completed. Activities completed to date include casting the 24-ton and 9-ton concrete cubes, placement of the cubes on the lower portion of the slope, casting the toe wall itself and installation of the liner and gravel layers on the slope (Figures 3 & 4). Future activities include installation of rock anchors, placement of cubes on the slope, and restoring the site. The construction is expected to be completed in December 1999.

DRAFT LANDFILL COVER DESIGN

The draft 100% landfill cover design is currently in review with the regulatory agencies. The cap includes a low permeability liner and a vegetative layer designed to accommodate native plants and trees (Figure 5). A pilot test concerning the vegetative layer is currently underway in cooperation with the University of Guam. The pilot test will determine whether root damage will occur to the liner from trees. Construction on the landfill cover is expected to begin in January/February 2000.



CLEANUP AT THE SOUTH FINEGAYAN CONSTRUCTION BATTALION LANDFILL U.S. NAVY PUBLIC WORKS CENTER, GUAM

Fact Sheet No. 9

Page 1

October 1999

This Fact Sheet describes the ongoing cleanup of contamination at U.S. Public Works Center (PWC) Guam under the Installation Restoration (IR) Program. This is one in a series of informational flyers that will be issued periodically throughout the cleanup process.

Background

The CB Landfill is located within a portion of the former NCTAMS Finegayan (operated by PWC) near the South Finegayan Housing Unit, approximately 1,100 feet west of the intersection of Park Road and Coral Tree Drive (Figure 1). The disposal area is located within a sinkhole and covers an area of approximately 2.6 acres. The site was used from 1944 until 1957 as a disposal area for wastes from the CB maintenance shop operated in the area.

Previous Environmental Investigations


A Site Investigation (SI) was conducted in 1991. The SI included a wetland survey, a soil gas survey, and the collection of groundwater samples. The SI recommended that the site move into the Remedial Investigation (RI) phase to assess the nature and extent of environmental contamination and to provide a preliminary screening of potential risks to human health and the environment.

The RI was completed in 1995 and concluded that surface soils at the landfill presents a potentially unacceptable risk to human and ecological receptors and recommended the presumptive remedy of landfill containment through capping. Based on the RI findings and recommendations, a non-time-critical Removal Action (RA) was conducted at the landfill.

As part of the RA, an Engineering Evaluation/Cost Analysis (EE/CA) was prepared to evaluate and recommend the cleanup alternatives. The recommended alternative was developed to minimize the infiltration of rainwater through landfill materials and to ensure that the landfill does not impact groundwater. The recommended cleanup alternative consists of an impermeable cap with flexible membrane liner, a surface water control system, and a landfill gas collection system which meets both federal and Guam the Environmental Protection Agency (EPA) requirements for landfill containment.

Removal Action

Construction of the impermeable cap for the landfill was completed in June 1998. A post maintenance plan was



developed in April 1999 to ensure that the landfill containment system would be properly maintained. Maintenance activities will consist of regular inspection of the landfill cap and trench, as well as monitoring for possible landfill gas. The post maintenance plan includes monitoring for possible lateral flow of infiltration from the perimeter swale towards the landfill.

Groundwater Monitoring Program

A groundwater monitoring work plan was also developed in April 1999 to ensure the landfill containment system is effective in minimizing impact to groundwater below the landfill. The groundwater monitoring work plan proposes to conduct a baseline groundwater sampling and analysis, a dye tracer study and a groundwater monitoring program.

The baseline groundwater sampling was conducted in May 1999 which established water quality parameters from seven groundwater discharge points, six springs and Lost Pond, located on the coastline (Figure 2) and seven monitoring wells on the site (Figure 3). The baseline results for concentrations of the metal contaminants were lower than EPA's maximum contaminant levels (MCLs) and action levels for drinking water.





Updates on Progress of Installation Restoration (IR) Sites in Guam

Restoration Advisory Board Meeting
October 6, 1999
Darlene Ige

Carpentry Shop Dip Tank (PWC)



- Dip Tank, drain lines, and sump were removed in Feb 1998
- Final Field Sampling Plan and Quality Assurance Project Plan Addendum completed in May 1999
- First round of additional groundwater sampling conducted in July 1999

Dry Cleaning Shop (COMNAVMARIANAS)



- Remedial Investigation (RI) Report finalized in Feb 1996
- Additional groundwater sampling planned for 2000

Building 3009 (PWC)



- Removal Action to treat PCB contaminated soil completed in Mar 1997
- Additional soil sampling was completed in Nov 1998
- Remedial Verification Report completed in Dec 1998
- RI to characterize the site planned for 2001

USS Proteus Fire Fighting Training Area (COMNAVMARIANAS)




- 2 USTs and burn pit soil removed in Oct 1997
- Soil treated by bioremediation in Feb 1998
- Final Decision Document for Site Closeout completed in Sep 1999

Lower Sasa Fuel Burning Pond, COMNAVMARIANAS



- Engineering Evaluation/ Cost Analysis (EE/CA) finalized in Dec 1997
- Draft Removal Action
 Design completed in Aug
 1998
- Revised ecological risk assessment completed in late Jan 1999
- Additional sediment sampling planned for early 2000

Area Behind the Fence (COMNAVMARIANAS)



- Remedial Investigation finalized in 1995
- Additional sampling planned for 2006


NEX Garage Septic Tank Site (COMNAVMARIANAS)



- EE/CA finalized in March 1998
- Alternative revised in final EE/CA
- Draft Action Memo completed in March 1998
- Draft Field Sampling Plan completed in June 1998
- Cleanup planned for 2000

South Finegayan Construction Battalion Landfill (PWC)

- Completed construction in June 1998
- Final General Site Work Plan for groundwater monitoring program completed in April 1999
- Dye Trace Study conducted in July 1999



Orote Landfill (COMNAVMARIANAS)



- Field work to construct the seawall started in March 1999
- Draft design for the landfill cap available for review in Sep 1999

Navy Installation Restoration (IR) Sites Quarterly Updates

Site Name Lower Sasa Fuel	Description	Site Information	IR Document	To-A A
Lower Sasa Fuel Burning Pond, COMNAVMAR (formerly FISC Guam)	The Lower Sasa Fuel Burning Pond was used from early 1959 to 1970 as a collection pond and burn pit for waste petroleum, oil and lubricants generated from various Navy activities. The pond received waste from an oil/water separator which developed mechanical problems allowing oily waste water to drain into the holding pond. Water at the bottom of the pond was drained into the adjacent wetlands via drainage channel and the remaining petroleum residue was then burned.	Surface water and groundwater and a 11 1 1	Final Engineering Evaluation/Cost Analysis (EE/CA) Report (Dec 1997) Final Action Memorandum (Aug 1998) Draft Removal Action Design (Aug 1998)	additional
		Surface water and groundwater, surface soil and subsurface soil, sediment and biological samples were collected and analyzed to determine the extent of contamination. Several metals including hexavalent chromium and organotin, total extractable petroleum hydrocarbons such as diesel and lubricant oils, polynuclear aromatic hydrocarbons (PAHs), polychlorinated biphenyls (PCBs) and chlorinated pesticides were detected in various surface/subsurface soil and sediment samples. Some metals were also detected in groundwater samples taken from the looped road disposal area. The results of the human health risk assessment concluded that the site does not pose a risk to humans. However, the ecological risk assessment identified a significant risk to ecological receptors at the sandblast grit peninsula and the loop road disposal area. These two areas also act as a source of contamination to the adjacent wetlands		A Removal Site Evaluation (RSE) and EE/CA is scheduled for FY 2006

		Site Information	IR Document	Future Activities
Site Name	Description	via surface water migration which poses significant risks to ecological receptors in the wetlands.		•
Building 3009, PWC Guam	Building 3009 was used as an electrical transformer repair shop from 1950 to 1977. Electrical transformers were overhauled there which involved the cleaning and repairing of parts and the recycling of transformer oils. Four storage tanks were located beside the building with two filtering systems; one for mineral oil and the other for PCB oil. In 1977, the PCB filter system and piping were removed due to leakage from the PCB storage tank.	Soil samples taken around the building and along a portion of the nearby drainage ditch identified significant polychlorinated biphenyls (PCB) contamination. A Removal Action was performed using the Base Catalyzed Decomposition Process (BCDP) due to the high levels of PCB detected at the site. A Remedial Investigation (RI) will be conducted to further characterize this site. Additional soil samples were taken in Nov 1998 to determine the extent of 2 hot spots.	Final Remedial Verification Report (Dec 1998).	A Remedial Investigation (RI) is scheduled for FY 2001
Carpentry Shop Dip Tank, PWC Guam	The Carpentry Shop Dip Tank Site was used continuously from 1953 to 1972 and sporadically until 1979 to preserve wood. Pentachlorophenol (PCP) and other preservatives including metal salt solutions (containing arsenic, chromium, copper, and zinc); aromatic-based oil and methylene chloride (possibly as a carrier for PCP) were the wood preservative used. The dip tank consisted of a below-grade vault made of steel reinforced concrete. Wood was dipped in a wood preservative solution and allowed to drip dry. Drippings landed on an adjacent concrete slab that drained to the dip tank or a large unpaved ditch via a concrete gutter. The dip tank vault was left in place and backfilled level with the ground surface, the drying rack and above ground storage tank were removed in 1979.	Groundwater, sediment and surface and subsurface soil samples were collected and analyzed to determine the extent of contamination. volatile organic compounds (VOCs), pentachlorophenol (PCP), polynuclear aromatic hydrocarbons (PAHs), dioxins, fuel hydrocarbons and elevated concentrations of arsenic, chromium, copper, and zinc were detected on this site. The contaminants were primarily detected in surface sediment, surface and subsurface soil and groundwater samples. The preliminary results of the human health risk and ecological risk assessments indicate that the site does not pose a significant risk to humans nor to the environment. The first round of groundwater sampling was conducted in July 1999.	Draft Remedial Investigation (RI) Report (Jul 1995) Final Field Sampling Plan and Quality Assurance Project Plan Addenda (May 1999)	Based on comments on the RI Report from the regulators, additional groundwater sampling is required. The second round of groundwater sampling is planned for January 2000. Incorporate results from the additional groundwater sampling into the Final RI report.

Site Name	Description	Site Information		
South Finegayan CB Landfill, PWC Guam	The Construction Battalion (CB) Landfill site was used from 1944 to 1959 as a disposal area for wastes from the CB maintenance shop operated in the area. Scrap metal, waste oil, and solvents, lead-based paints, tires and equipment parts were disposed at the site. The wastes observed in the landfill include concrete and metallic construction debris, glass bottles, tires, and vehicle parts, pipes, domestic wastes, and burned liquid and solid wastes. Additionally, the pesticide DDT was heavily applied to the site.	Ground water samples contained elevated concentrations of some metals and low levels of VOCs and semi-volatile organic compounds which are common laboratory contaminants. The results of the human health risk and ecological risk assessments determined that a significant risk exists to humans and the environment via contact with surface soil at the site. The installation of a geosynthetic landfill cap was completed in June 1998 and the baseline groundwater compiler.	(Jan 1998) Final Draft Remedial Verification Report (RVR) (Jul 1999) Final General Site Work Plan for Groundwater Monitoring Program	Future Activit Maintenance as groundwater monitoring will continue to ensu cap integrity.
ite, OMNAVMAR formerly AVACTS) (i) st tr be lei as	torage (possibly for water softening reatment). The investigation was initiated ecause solvents were believed to have taked from USTs or dumped on the ground a sludge. The solvents may then move to be groundwater.	was conducted in July 1999. Soil, wetland sediment, and groundwater samples were collected and analyzed to determine the extent of contamination. Tissue samples from organisms present near the site were also at 1	(Apr 1999) Final Remedial Investigation (RI) Report (Feb 1996)	Based on the comments on the RI Report from the regulators in 1997, additional groundwater sampling is required. Additional groundwater sampling is planned for 2000.

Site Name	Description	Site Information	IR Document	Future Activities
Orote Landfill,	The Orote Landfill occupies approximately	Surface and subsurface soil samples, groundwater and seawater	Final Engineering	In addition to the
COMNAVMAR 9	9.4 acres of land. It was used for the	samples, and marine tissue samples were collected to determine the	Evaluation/ Cost	installation of a
(formerly	disposal of residential, industrial, and	nature and extent of contamination at the Orote Landfill.	Analysis (EE/CA)	landfill cap, a
	construction wastes from approximately		(Feb 1999)	seawall was
	1944 to 1969. The face of the cliff that	Soil within the site boundaries have elevated concentrations of		designed to
	surrounds the landfill was reportedly the	PCBs, pesticides, TFHs, PAHs, VOCs, and metals. Low levels of	Final 100%	prevent erosion of
1	most active disposal area. Flammable	dioxins were detected in soil samples collected within the landfill,	Seawall Design	landfill material
1	material was burned, and the ashes were	but concentrations do not appear to be significantly elevated above	(March 1999)	into the ocean.
1	buried on the cliff above the nearby cove.	samples taken outside the landfill.		
]	Nonflammable materials were either buried	•	Approved Action	Construction of
1	behind the cliff or bulldozed over the cliff	The Human Health Risk Assessment (HHRA) concluded that site-	Memorandum	the seawall started
	onto the beach. The beach currently	related contamination does not appear to pose a significant	(April 1999)	in March 1999
(contains a large amount of rusted metal and	carcinogenic risk to human health. However, site related		and is scheduled
	other debris.	contamination does present a non-carcinogenic hazard to human	Final Site Work	for completion in
		health. The modes of exposure are primarily through ingestion of	Plan for Seawall	Dec 1999.
		soil, direct contact with soil and ingestion of organisms from the	Construction	A D
		site.	(April 1999)	A Revegetation Pilot Test was
		T. 1161 G. C. C. C. C. C. L. C. L. C. L. C. L. C.	Final	started in Sep
		In addition, Screening Ecological Risk Assessment (SERA) was	Revegetation Plan	1999.
		conducted under the Removal Site Evaluation (RSE). The RSE concluded that although the groundwater may be slightly impacted	(April 1999)	1999.
		by the landfill, the risk to sea life from groundwater at the site is not	(April 1977)	
		significant based on a detailed risk assessment.	Final Pilot Test	
		Significant based on a detailed risk assessment.	Work Plan	
		Construction of the seawall started in March 1999.	(Aug 1999)	
		Construction of the seawan started in whaten 1999.	(riug 1777)	
			Draft Landfill Cap	
		·	Design Package	
			(Sep 1999)	
USS Proteus	The USS Proteus Site was the site of a	Soil, groundwater, marine sediment were collected and analyzed to	Closure Report	
1 000	former fire fighting training pit and two	determine the extent of contamination. Tissue samples from	(July 1998)	
, , ,	underground fuel tanks. Fire fighting	organisms present near the site and sediment bioassay were also	(,)	
	training exercises were performed at USS	conducted.	Final Decision	
1 ,	Proteus from 1965 to 1969. In these		Document	
	exercises, 55-gallon drums or pontoons were	Two primary areas had elevated levels of contamination: (1) the	(Sep 1999)	
	cut in half, filled with diesel fuel and	USTs area consisting of a gasoline and a diesel tank, the contents of		
	gasoline (supplied by the underground fuel	which were pumped out in April 1994, and (2) a fire fighting	·	
	tanks) and then ignited.	training burn pit area consisting of wire mesh and charred soils.		

Site Name	Description	Site Information	IR Document	Future Activities
		Although no evidence of fuel leakage from the USTs was detected, elevated PAHs were detected around the vent pipes above the USTs. The contamination above the USTs was thought to be the result of spillage or overfilling. The burn pit area had elevated levels of TFHs and VOCs. No significant groundwater contamination was found at the Proteus Site.		
·		The two underground fuel tanks and the contaminated soil in the burn pit were excavated and removed in October 1997. Samples were taken to ensure that the cleanup goals are met. The excavation pits were backfilled with clean materials and the site was restored to the original grade. The contaminated soil was treated by bioremediation in February 1998. No further cleanup action is planned for this site.		
NEX Garage Septic Tank Site, COMNAVMAR (formerly NAVACTS)	The septic tank is a subsurface structure, made of concrete. The septic tank was connected to a waste oil underground storage tank (UST) via an underground pipeline. The waste oil UST was removed in 1987. Another pipeline connected to this septic tank ran out to Agat Bay. From 1955 to 1975, waste oils, automotive fluids, and cleaning solvents which were generated at the NEX Garage Septic Tank Site were disposed of in the waste oil UST.	Soil, groundwater, pipeline sediment, septic tank, marine sediment and biological tissues were collected and analyzed to determine the extent of contamination. Soil and sediment bioassay were also conducted. Low levels of TFHs and PCBs were found in the former waste oil tank area. Low levels of TFHs, PAHs, and some pesticides were found within the pipeline through a manhole access, but no significant levels were found outside the sewer pipeline. Petroleum sludge was found within the concrete septic tank, no significant releases were found to have occurred outside the septic tank. The study concluded that there was no existing threat to human health and environment. The Engineering Evaluation/Cost Analysis (EE/CA) recommended the removal of the septic tank and the oily sludge in the septic tank, cleaning and removing the pipeline between Route 2 and the NEX Garage, and cleaning, capping and closing in place the pipeline between Route 2 and Agat Bay.	Final Engineering Evaluation/Cost Analysis (EE/CA) (Mar 1998) Draft Action Memorandum (Mar 1998) Draft Field Sampling Plan for Post-Removal Confirmation Sampling (June 1998)	After the Action Memorandum is finalized to document the selected alternative, a Work Plan will be prepared for the actual cleanup. The cleanup is planned to start in 2000.