# DEPARTMENT OF THE NAVY COMMANDER, FLEET ACTIVITIES, YOKOSUKA



#### COMMANDER, FLEET ACTIVITIES, YOKOSUKA PSC 473 BOX 1 FPO AP 96349-0001

COMFLEACTINST 5090.14 N4E

DEC 1 2 2011

### COMFLEACT YOKOSUKA INSTRUCTION 5090.14

From: Commander, Fleet Activities, Yokosuka

Subj: LEAD BASED PAINT PROGRAM MANAGEMENT

Ref: (a) COMFLEACT, Yokosuka, Lead Based Paint Management
Plan

- (b) Japan Environmental Governing Standards
- (c) OPNAVINST 1700.9E
- (d) OPNAVINST 5100.23G
- (e) BUMEDINST 6200.14B
- (f) NAVFAC/BUMED Policy Letter, Lead Based Paint Assessment Program Disclosure for Navy Family Housing
- (g) NAVFAC Engineering Service Center Technical Report, TR-2254-ENV
- (h) NAVFACENGCOM Letter 11101
- 1. <u>Purpose</u>. To promulgate reference (a) to all personnel and commands within Commander, Fleet Activities (COMFLEACT), Yokosuka Area of Responsibility (AOR).
- 2. <u>Scope</u>. Reference (a) integrates the requirements and information contained in references (b) through (h) and defines the proper protection and management with respect to Lead Based Paint (LBP).
- 3. <u>Applicability</u>. This instruction applies to all commands, activities, and personnel working and living within the COMFLEACT, Yokosuka AOR.

# 4. Responsibilities

# a. Lead Based Paint Program Manager

- (1) Serve as single point of contact for LBP related activities in accordance with reference (b).
- (2) Work closely with installation Military Family Housing (MFH) and child occupied facilities to ensure compliance with applicable LBP regulations in accordance with reference (b).

# DEC 1 2 2011

- (3) Lead the implementation of the multi-disciplinary LBP hazard management program in accordance with reference (b).
- (4) Complete an annual review and update of the installation LBP management program plan in accordance with reference (b).

# b. Department of Defense Dependent Schools

- (1) Maintain work order histories in accordance with reference (b).
- (2) Perform inspections as part of facility manager responsibilities in accordance with reference (b).
  - (3) Submit work orders in accordance with reference (b).
- (4) Disclose to parents the presence of LBP and LBP hazards in accordance with reference (b).
- (5) Notify parents of any remodeling and renovation projects in accordance with reference (b).
- (6) Provide facility personnel U.S. Department of Housing and Urban Development (HUD) Visual Assessment Training in accordance with reference (b).

#### c. Military Family Housing

- (1) Manage the LBP program for MFH in accordance with reference (h).
- (2) Maintain work order histories in accordance with reference (b).
- (3) Perform visual assessments of MFH in accordance with reference (b).
  - (4) Submit work orders in accordance with reference (b).
- (5) Maintain the LBP inventory survey records for MFH in accordance with references (b), (f) and (h).
- (6) Disclose to residents the presence of LBP and LBP hazards and information in accordance with reference (b).

- (7) Ensure resident notification occurs for any remodeling and renovation projects in accordance with reference (b).
- (8) Provide MFH inspectors the HUD Visual Assessment Training in accordance with reference (b).

# d. Fleet Activities (FLEACT), Yokosuka Morale, Welfare and Recreation Child Development Centers

- (1) Maintain work order histories in accordance with reference (b).
- (2) Perform inspections as part of facility manager responsibilities in accordance with reference (b).
  - (3) Submit work orders in accordance with reference (b).
- (4) Disclose to parents the presence of LBP and LBP hazards in accordance with reference (b).
- (5) Notify parents of any remodeling and renovation projects in accordance with reference (b).
- (6) Provide facility personnel HUD Visual Assessment Training in accordance with reference (b).
- (7) Ensure inspections are conducted in accordance with reference (c).
- (8) Ensure cleanings are conducted in accordance with reference (c).

# e. FLEACT, Yokosuka Public Works Department

- (1) Evaluate work requests to determine if lead containing materials will be disturbed in accordance with reference (g).
- (2) Manage in place and maintain undamaged LBP in good condition, repair or remove damaged LBP, and replace removed LBP with lead-free materials in accordance with reference (g).
- (3) Ensure LBP sampling is performed by U.S. Environmental Protection Agency (EPA) trained personnel (contractor or in-house) in accordance with reference (g).

# DEC 1 2 2011

- (4) Develop interim controls or abatement projects to repair, remove, encapsulate, enclose or maintain damaged or deteriorated LBP in accordance with references (b) and (q).
- (5) Ensure LBP project specifications are developed using Unified Facilities Guide Specifications and prepared by trained personnel in accordance with references (b) and (g).
- f. FLEACT, Yokosuka Public Works Department, Environmental Division
- (1) Provide regulatory support, oversight and direction for LBP in accordance with reference (b).
- (2) Perform Environmental Quality Assessments of the LBP Management Program in accordance with reference (b).
- (3) Ensure Environmental personnel receive proper LBP training in accordance with reference (b).
- (4) Review work orders and LBP management plans in accordance with reference (b).
- g. <u>U.S. Naval Hospital (NAVHOSP)</u>, Yokosuka. Operate the Pediatric Lead Poisoning Prevention Program in accordance with reference (e).
- h. NAVHOSP, Yokosuka, Industrial Hygiene Department. Perform monitoring, controls and surveillance in accordance with reference (d).

# i. <u>Installation and Tenant Command Safety Departments</u>

- (1) Perform responsibilities for worker protection in accordance with reference (d).
- (2) Conduct annual inspections of Child Development Centers in accordance with reference (d).
- (3) Assist in reviewing contractor submittals, and participate in pre-construction conferences in accordance with reference (d).

Man

COMFLEACTINST 5090.4B

# DEC 1 2 2011

Distribution: COMFLEACTINST 5215.2K Lists I & II, Case 1

Stocked: Commander Fleet Activities, Yokosuka PSC 473, Box 1 FPO AP 96349-0001